



### Annexure III

#### 1. Sanitary Inspection Form for Piped Water

##### I. Type of Facility PIPED WATER

- 1. General Information: Zone: 'A' Area: 3.
- 2. Code Number Chittaranjan (D. V. Girls)
- 3. Date of Visit 10.08.2023. School.
- 4. Water samples taken? ~~0/1~~ Sample Nos. ....1.....

##### II. Specific Diagnostic Information for Assessment

(Please indicate at which sample sites the risk was identified) Risk Sample No

- 1. Do any tapstands leak? Y/N ..... *M*.....
- 2. Does surface water collect around any tapstand? Y/N ..... *M*.....
- 3. Is the area uphill of any tapstand eroded? Y/N ..... *M*.....
- 4. Are pipes exposed close to any tapstand? Y/N ..... *M*.....
- 5. Is human excreta on the ground within 10m of any tapstand? Y/N ..... *M*.....
- 6. Is there a sewer within 30m of any tapstand? Y/N..... *Y*.....
- 7. Has there been discontinuity in the last 10 days at any tapstand? Y/N ..... *M*.....
- 8. Are there signs of leaks in the mains pipes in the Parish? Y/N..... *M*.....
- 9. Do the community report any pipe breaks in the last week? Y/N ..... *M*.....
- 10. Is the main pipe exposed anywhere in the Parish? Y/N ..... *M*.....

Total Score of Risks *0/10*

Risk score: 9-10 = Very high; 6-8 = High; 3-5 = Medium; 0-3 = Low

##### III. Results and Recommendations:

The following important points of risk were noted :( list nos. 1-10)

Signature of surveyor: *Debasis Mandal*

Comments: ..... *12/05/2023* .....

.....  
No Growth after  
48 hours of incubation  
at 37°C Temperature  
.....

*Bacteriologically satisfactory.*